



Inventory Report

Prepared by Click Inventories



Condition report

Sample report: photo link disabled for illustration.

 Click for photos

 [clickinventories.com](https://www.clickinventories.com)

 0203 488 8072



PROPERTY

Flat 12, Sample House, 1 Specimen Square, London

PREPARED FOR

Sample Lettings Ltd

PROPERTY TYPE

2 Bedroom Apartment
1 Bathroom. Furnished

REFERENCE

SAMPLECO

INVENTORY DATE

02/02/2026

AMENDMENTS ADMISSIBLE UNTIL

23/02/2026

PHOTOGRAPHS

62

ADDITIONAL AREAS

Balcony	1
Storage cupboard	1
Garden	N/A

CONTENTS

Disclaimer	2	Findings	29
Electricals and Fire Safety	3	Photos	33
Cleanliness	4	Bedroom Two	36
Glossary of Terms	5	Findings	37
Condition Summary	6	Photos	41
Fire Safety	8	Bathroom	44
Keys & Manuals	9	Findings	45
Meter Readings	10	Photos	49
Report Findings	11	Hallway Storage Cupboard	52
Entrance and Hallway	11	Findings	53
Findings	12	Photos	56
Photos	15	Balcony	59
Reception and Kitchen	18	Findings	60
Findings	19	Photos	62
Photos	25	Signatures	65
Bedroom One	28		

DISCLAIMER

This inventory report provides a fair, unbiased and accurate record of the contents and internal condition of the property. It is the responsibility of the landlord and tenant or the respective agents to agree between themselves on the accuracy of this report.

Electric sockets, switches, telephone points and aerial points are in white plastic unless stated otherwise. Windows are not tested, and no comment is made on their operational order. Unless agreed beforehand, property left in lofts, cellars and locked rooms will not be included in the inventory report and remain the sole responsibility of the landlord. Meter readings will be taken if the meters are easily accessible.

All static, loose or movable items in this inventory are listed as far as possible from left to right starting at the main door. Multiple items may be grouped together and may require locating. Light fittings are assumed to come complete with a serviceable bulb(s) unless stated. All electrical items are considered complete with plugs, bulbs and flexes unless otherwise specified. Settling cracks to walls and ceilings are accepted and will not be mentioned unless necessary. All measurements given are approximate.

No attempt has been made to identify any item by its original manufacturer or the period in which it was produced. The inventory clerk preparing the report is neither a qualified surveyor nor an expert on fabrics,

woods, materials or antiques.

The report relates only to furniture, furnishings and all of the landlord's equipment and contents in the property. It is no guarantee of, or report on, the adequacy of, or safety of any such equipment or contents. It is a documented record that such items exist within the property, at the date of the inventory and the superficial condition of the same.

Furniture Where the inventory states 'FFR seen', this is taken that labels are present on items of furniture that indicates these items comply with the Furniture and Furnishings (Fire) (Safety) Regulations 1988 - as amended 1993. It is however not the responsibility of the inventory clerk to state that these items do comply with these regulations.

Heavy items of furniture such as kitchen appliances, wardrobes and beds, will not be moved and the inventory clerk will not be responsible for the condition of any flooring underneath, or areas surrounding such items, that cannot be seen. Mattresses will not be flipped or touched by our clerks, meaning no observations below the mattress will be reported.

IMPORTANT: Any discrepancies or requested amendments must be advised in writing to the issuing agent within 14 working days from the day the tenant(s) received the report. If no amendments are advised within this time-scale, any future discrepancies or requested amendments will not be admissible and the report will be deemed as accepted full and final by both landlord/ managing agent and tenant.

ELECTRICALS AND FIRE SAFETY

Any electrical appliances, smoke alarms, CO2 detectors, electrical items or fittings will be tested for power supply only either by Self-test button audible check (beep test) or visual check of power LED light where practical or easily accessible.

Where the inventory notes the presence of smoke alarms and carbon monoxide detectors, if tested by the inventory company, this will be for power supply and should not be interpreted to mean that these items are fully working and that the property complies with the 2015 regulations. The Inventory Company will take no responsibility for damage or malfunction during the testing of such alarms.

Boilers, gas fires, water supply, fire alarms and radiators are not tested. With electrical appliances, an account will not be given as to the efficiency or safety of the items, we merely state that such an item

exists at the property and the current condition.

The Fire and Safety regulations regarding furnishings, gas and electrical items alike are the responsibility of the Landlord. Where the Inventory notes that an FFR label is seen this should not be interpreted as the item complies with the fire and furnishings (Fire) (Safety) (Amendments) 1993. It is merely a record that the item had a label as described or similar to that detailed in the guide to the regulations as published by the Department of Trade and industry, January 1997 (or subsequent edition), attached at the time the inventory was compiled.

Ensuring compliance with the new regulations any remedial action required remains the responsibility of the Landlord or their managing agent.

CLEANLINESS

If the property was professionally cleaned for the tenancy it is strongly advised that professional cleaners are used to carry out an end of tenancy clean. It is expected that the property and its contents will be in a similar condition of cleanliness as noted in the original inventory. If the standard of cleaning is not satisfactory, most managing agents or landlords will employ a contract cleaner - the cost of which will be deducted from the tenant's deposit. Where professional cleaners are used, receipts should be retained and produced if required. All cleaning must be thorough, and the property left tidy at the end of the tenancy. The main areas for concern are set out below:

Carpets and flooring Carpets should be professionally cleaned before the end of a tenancy in accordance with the inventory or tenancy agreement and vinyl/tiled flooring should be left clean and free from cracks or tears.

Curtains and décor Curtains should be professionally cleaned before the end of a tenancy in accordance with the inventory or tenancy agreement. The decor throughout the property should be in the same state and condition as at the start of the tenancy as detailed within the original inventory. Charges may be incurred if picture hooks, nails, screws or screw holes etc. have been added and not removed and the area made good. Charges may also be incurred where excessive wear is noted. Remove finger prints and excessive marks from the decor. Whilst reasonable wear and tear is expected, your fingerprints to walls and doors is quite clearly a cleaning issue.

Appliances Refrigerators/Freezers should be defrosted and left switched off and open to avoid smelling. Ovens, hobs, extractor hoods, and microwaves should be cleaned of burnt on deposits and grease and doors/seals cleaned. Tumble dryers, washing machines and dishwashers should have filters emptied, soap drawers cleaned of deposits and doors/seals cleaned.

Mould and mildew - There are two types of mould and mildew that can develop during a tenancy: (1) Low level damp penetration to outer walls normally creeping up the walls from the bottom. In most cases this indicates a maintenance issue for the landlord and (2) High level mould normally seen on ceilings, silicone sealant around bath fittings and window frames. This is almost certainly caused by a combination of high humidity and lack of ventilation. In either case, the problem should be kept under control or even eradicated by using a good quality proprietary treatment readily available from retailers.

Gardens where applicable should be left in a neat and tidy order, the lawns having been cut, borders and planters weeded, hedges trimmed, and pathways/patios weeded and swept.

Allowances are made for fair wear and tear but it should be noted that areas that are not clean will not be considered as fair wear and tear.

GLOSSARY OF TERMS

CONDITION

Good Condition	Light signs of wear, minor marks or scratches, no obvious defects.
Visually safe	Recorded where an electrical item or fitting has been checked visually for damage. It is not a statement of electrical safety.
Not tested	Recorded where an item has not been tested, in line with the Electricals and Fire Safety section.

ABBREVIATIONS

FFR Fire label

Only the terms used in this report are defined above.

CONDITION SUMMARY

SCHEDULE OF CONDITION			YES / NO	COMMENT
1	General cleanliness	Do any areas require further cleaning?	NO	Property professionally cleaned following the end of tenancy works.
2	Flooring	Do any areas require further cleaning?	NO	
3	Windows	Do any areas require further cleaning?	NO	
4	Blinds	Are they all working?	YES	
5	Curtains	Do any areas require further cleaning?	NO	
6	Linen	Does all linen appear freshly laundered?	YES	
7	Furnishing	Do any areas require further cleaning?	NO	
8	Bathroom	Do any areas require further cleaning?	NO	
9	Kitchen	Do any areas require further cleaning?	NO	
10	Appliances	Do any require further cleaning?	NO	
11		Do the appliances work?	YES	All appliances tested, in working order.
12	Interior lighting	Were all bulbs working when tested?	YES	
13	Smoke alarms	Were all alarms working when tested?	YES	All smoke and heat alarms tested, in working condition.
14	Manuals	Could any be seen?	YES	Appliance manuals and the building handbook in the kitchen island top drawer.
15	Tenant present	Was the tenant present for the inventory?	NO	Inspection carried out unattended.
16	Interior drains	Do they run clear when tested?	YES	
17	Outside areas	How did they appear?	CLEAN	Balcony clean and tidy.
18	Rubbish	Has all rubbish been cleared?	YES	

CONDITION SUMMARY

SCHEDULE OF CONDITION		YES / NO	COMMENT
19	Non-visible notations	Do any areas have odours or notable smells?	NO


FIRE SAFETY

ITEM	LOCATION	COMMENTS
Smoke alarm	Entrance and Hallway	Tested, in working condition
Heat alarm	Entrance and Hallway	Tested, in working condition
Smoke alarm	Reception and Kitchen	Tested, in working condition
Heat alarm	Reception and Kitchen	Tested, in working condition
Fire blanket	Reception and Kitchen, inside the tall unit beside the oven	In position. Not tested.
Sprinkler heads	Throughout the apartment, ceiling recessed	In position. Not tested.
Front door closer	Entrance and Hallway	In position.

Keys & Manuals

ITEM	QTY	DESCRIPTION
Keys	1	set with 2 x security keys and 1 x black key fob on a brushed brass ring with a blank leather tag.
Manuals		Manuals: appliance manuals and the building handbook in a folder in the kitchen island top drawer.

Key Photographs



Keys

02/02/2026

METER READINGS

TYPE	READING	LOCATION	SERIAL
Electricity	04512.3	Hallway storage cupboard	E17SAMPLE1234
Water	00821	Hallway storage cupboard	W21SAMPLE5678
Gas	03367	Hallway storage cupboard	G4SAMPLE9012

Meter Photographs



Electricity

02/02/2026



Water

02/02/2026




Gas

02/02/2026

Report Findings

ENTRANCE AND HALLWAY



NOTE ANY RECENT WORKS

None advised at the time of inspection.

KEY


- Doors
- Storage cupboard
- Alarms



Doors x1



Storage cupboard x1



Alarms x2

Entrance and Hallway

ENTRANCE AND HALLWAY

FINDINGS

ITEM	QTY	DESCRIPTION	CONDITION COMMENTS
DOORS AND WINDOWS			
1	Door and features	1	Walnut veneer fire door to the communal corridor, warm white painted to the interior
			Exterior: brushed brass numeral 12, spy hole and lever handle, multi-point lock
			Interior: brushed brass lever handle, thumb turn and overhead closer
2	Door frame	1	Walnut veneer to the exterior, warm white painted timber to the interior
3	Threshold	1	Brushed brass threshold strip beneath the door
4	Windows		Nil recorded
FLOORING, WALLS AND CEILING			
5	Flooring		Wide-plank oak herringbone floor, matt lacquered
6	Skirting		Warm white painted timber with a recessed shadow gap

ENTRANCE AND HALLWAY

FINDINGS

ITEM	QTY	DESCRIPTION	CONDITION COMMENTS
FLOORING, WALLS AND CEILING			
7	Walls	Warm white painted	Good condition, no marks or defects noted
8	Ceiling	Warm white painted	Good condition, no marks or defects noted
FIXTURES AND FITTINGS			
9	Lighting	4 Recessed ceiling downlights with brushed brass trims, dimmable	Tested, in working order. All 4 in working order
10	Smoke alarm	1 Ceiling mounted white plastic mains powered alarm	Tested, in working condition
11	Heat alarm	1 Ceiling mounted white plastic mains powered alarm, beside the kitchen entrance	Tested, in working condition
12	Video entry phone	1 Wall mounted white glass touchscreen unit	Good condition, no marks or defects noted. Tested, in working order
13	Thermostat	1 Wall mounted white glass digital thermostat for the underfloor heating	Good condition, no marks or defects noted. Not tested
14	Heating	Underfloor heating beneath the herringbone floor, controlled by the wall thermostat	Good condition, no marks or defects noted. Not tested

ENTRANCE AND HALLWAY

FINDINGS


ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS				
15	Switches	2	Brushed brass screwless light switch units, two functions each	Working condition. Visually safe
16	Sockets	1	Brushed brass screwless double plug socket unit at low level	Working condition. Visually safe
17	Fitted joinery	1	Full-height built-in coat cupboard, warm white matt lacquer doors with push-to-open catches Interior: brushed brass hanging rail and one oak shelf	Clean and good condition, no marks or defects noted
18	Mirror	1	Wall mounted round mirror with a slim brushed brass frame, above the console	Good condition, no marks or defects noted
DÉCOR AND FURNITURE				
19	Console table	1	Slim oak console table with brushed brass legs	Good condition, no marks or defects noted
20	Table lamp	1	Ceramic table lamp with a linen shade, on the console	Good condition, no marks or defects noted. Tested, in working order
21	Artwork	1	Framed abstract print in a light oak frame	Good condition, no marks or defects noted

Entrance and Hallway

PHOTOS



02/02/2026



Item 1 · Door and features

02/02/2026

Entrance and Hallway

PHOTOS



Herringbone floor at the entrance

Sample photograph placeholder

Item 5 · Flooring

02/02/2026



Ceiling smoke alarm

Sample photograph placeholder

Item 10 · Smoke alarm

02/02/2026



Built-in coat cupboard, doors open

Sample photograph placeholder

Item 17 · Fitted joinery

02/02/2026

Entrance and Hallway

PHOTOS



Video entry phone

Sample photograph placeholder

Item 12 · Video entry phone

02/02/2026



Mirror and console table

Sample photograph placeholder

Item 18 · Mirror

02/02/2026



Thermostat and switches

Sample photograph placeholder

Item 13 · Thermostat

02/02/2026

RECEPTION AND KITCHEN



Alarms x2



Windows x3



Balcony x1

NOTE ANY RECENT WORKS

None advised at the time of inspection.

KEY

- Alarms
- Windows
- Balcony

Reception and Kitchen

RECEPTION AND KITCHEN

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DOORS AND WINDOWS				
1	Door and features	1	Warm white painted solid timber door to both faces, flush finish, concealed hinges Brushed brass lever handles to both faces	Good condition, no marks or defects noted
2	Door frame	1	Warm white painted timber, exposed to both faces	Good condition, no marks or defects noted
3	Threshold	1	Solid oak threshold beneath the door	Good condition, no marks or defects noted
4	Window and features	3	Floor-to-ceiling aluminium framed double glazed windows, bronze finish to the exterior, one opening sliding door onto the balcony Brushed brass handles and locks to the sliding door	Good condition, no marks or defects noted. Not tested
5	Curtains	3	Floor length sheer linen curtains on ceiling recessed tracks	Clean and good condition, no marks or defects noted
FLOORING, WALLS AND CEILING				
6	Flooring		Wide-plank oak herringbone floor, matt lacquered	Clean and good condition, no marks or defects noted

RECEPTION AND KITCHEN

FINDINGS

ITEM	QTY	DESCRIPTION	CONDITION COMMENTS
FLOORING, WALLS AND CEILING			
7	Skirting	Warm white painted timber with a recessed shadow gap	Good condition, no marks or defects noted
8	Walls	Warm white painted	Recently redecorated. Good condition, no marks or defects noted
9	Ceiling	Warm white painted with a recessed perimeter lighting channel	Good condition, no marks or defects noted
FIXTURES AND FITTINGS			
10	Lighting	8 Recessed ceiling downlights with brushed brass trims, dimmable	Tested, in working order. All 8 in working order
11	Pendant lighting	3 Brushed brass and opal glass pendants above the kitchen island	Good condition, no marks or defects noted. Tested, in working order
12	Smoke alarm	1 Ceiling mounted white plastic mains powered alarm, to the reception	Tested, in working condition
13	Heat alarm	1 Ceiling mounted white plastic mains powered alarm, to the kitchen	Tested, in working condition
14	Heating	Underfloor heating beneath the herringbone floor	Good condition, no marks or defects noted. Not tested

RECEPTION AND KITCHEN

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS				
15	Switches	3	Brushed brass screwless dimmer switch units, two functions each	Working condition. Visually safe
16	Sockets	6	Brushed brass screwless double plug socket units, two with USB outlets	Working condition. Visually safe
17	Worktop		White quartz worktop and matching upstand, with a waterfall end to the island	Clean and good condition, no marks or defects noted
18	Kitchen units		Handleless soft grey matt lacquer wall and base units with soft close doors and drawers Island unit with four drawers and seating overhang to the reception side Interiors: white melamine shelves and drawer boxes, cutlery insert to the top drawer	Clean and good condition, no marks or defects noted
19	Sink	1	Undermounted stainless steel single bowl sink with a brushed brass mixer tap and boiling water tap	Clean and good condition. Both taps tested, in working order

RECEPTION AND KITCHEN

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS				
20	Hob	1	Black glass four zone induction hob, flush fitted to the island, touch controls	Recently cleaned. Clean, no marks or defects noted. Tested, in working order
21	Extractor	1	Ceiling recessed extractor above the island, brushed steel grille, remote controlled	Clean and good condition. Tested, in working order
22	Oven	1	Integrated black glass single electric oven with touch controls Interior: two chrome shelves and one enamel tray	Clean and good condition. Tested, in working order
23	Combination microwave	1	Integrated black glass combination microwave oven above the oven	Clean and good condition. Tested, in working order
24	Fridge freezer	1	Integrated tall fridge freezer behind soft grey lacquer doors Fridge: four glass shelves, two salad drawers and three door shelves. Freezer: three clear drawers	Clean and good condition. Tested, in working order
25	Dishwasher	1	Integrated full size dishwasher behind a soft grey lacquer door, two baskets and a cutlery tray	Clean and good condition. Tested, in working order

RECEPTION AND KITCHEN

FINDINGS

ITEM	QTY	DESCRIPTION	CONDITION COMMENTS	
FIXTURES AND FITTINGS				
26	Wine cooler	1	Integrated under counter wine cooler with a black glass door, five timber racks	Clean and good condition. Tested, in working order
27	Air conditioning	1	Ceiling recessed white linear air conditioning grille with a wall controller	Good condition, no marks or defects noted. Not tested
DÉCOR AND FURNITURE				
28	Sofa	1	Deep three seat sofa upholstered in ivory boucle, oak plinth base	Clean and good condition, no marks or defects noted. FFR label present.
			Four matching scatter cushions	
29	Armchair	1	Upholstered armchair in oatmeal linen with oak legs	Clean and good condition, no marks or defects noted. FFR label present.
30	Coffee table	1	Round white marble coffee table on a pedestal base	Good condition, no marks or defects noted
31	Side table	1	Round oak side table beside the armchair	Good condition, no marks or defects noted. FFR label present.
32	Rug	1	Oatmeal wool flatweave rug beneath the coffee table, approximately 2m by 3m	Clean and good condition, no marks or defects noted

RECEPTION AND KITCHEN

FINDINGS


ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DÉCOR AND FURNITURE				
33	Dining table	1	Round solid oak dining table seating four	Good condition, no marks or defects noted
34	Dining chairs	4	Oak framed dining chairs with oatmeal upholstered seats	Clean and good condition, no marks or defects noted. FFR label present.
35	Bar stools	3	Brushed brass framed bar stools with oatmeal upholstered seats, at the island	Clean and good condition, no marks or defects noted. FFR label present.
36	Media unit	1	Low oak media unit with two push-to-open doors	Good condition, no marks or defects noted
37	Floor lamp	1	Brushed brass arc floor lamp with a linen shade	Good condition, no marks or defects noted. Tested, in working order
38	Artwork	2	Framed abstract prints in light oak frames, above the sofa	Good condition, no marks or defects noted. FFR label present.

Reception and Kitchen

PHOTOS



02/02/2026



Item 18 · Kitchen units

02/02/2026

Reception and Kitchen

PHOTOS



**Close-up: induction hob
and touch controls**

Sample photograph placeholder

Item 20 · Hob

02/02/2026



Wall behind the sofa

Sample photograph placeholder

Item 8 · Walls

02/02/2026



**Integrated appliances,
doors open**

Sample photograph placeholder

Item 24 · Fridge freezer

02/02/2026

Reception and Kitchen

PHOTOS



Sofa and FFR label

Sample photograph placeholder

Item 28 · Sofa

02/02/2026



Dining table and chairs

Sample photograph placeholder

Item 33 · Dining table

02/02/2026




Sink and mixer tap

Sample photograph placeholder

Item 19 · Sink

02/02/2026


BEDROOM ONE



Doors x1



Windows x1



Wardrobes x1

Bedroom One

NOTE ANY RECENT WORKS

None advised at the time of inspection.

KEY

- Doors
- Windows
- Wardrobes

BEDROOM ONE

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DOORS AND WINDOWS				
1	Door and features	1	Warm white painted solid timber door to both faces, flush finish, concealed hinges Brushed brass lever handles to both faces	Good condition, no marks or defects noted
2	Door frame	1	Warm white painted timber, exposed to both faces	Good condition, no marks or defects noted
3	Threshold	1	Solid oak threshold beneath the door	Good condition, no marks or defects noted
4	Window and features	1	Floor-to-ceiling aluminium framed double glazed window, one tilt and turn opening section Brushed brass handle and lock	Good condition, no marks or defects noted. Not tested
5	Window reveal	1	Warm white painted plaster reveal and oak sill board to the window	Recently treated and painted. Good condition, no marks or defects noted
6	Curtains	1	Floor length sheer linen curtains on a ceiling recessed track Oatmeal blackout curtains on a second track	Clean and good condition, no marks or defects noted

BEDROOM ONE

FINDINGS

ITEM	QTY	DESCRIPTION	CONDITION COMMENTS
FLOORING, WALLS AND CEILING			
7	Flooring	Oatmeal wool carpet, fitted wall to wall	Recently cleaned. A faint shadow remains where the stain beside the bed was, approximately 10cm. Otherwise good condition
8	Skirting	Warm white painted timber with a recessed shadow gap	Good condition, no marks or defects noted
9	Walls	Warm white painted	Good condition, no marks or defects noted
10	Ceiling	Warm white painted	Good condition, no marks or defects noted
FIXTURES AND FITTINGS			
11	Lighting	4 Recessed ceiling downlights with brushed brass trims, dimmable	Tested, in working order. All 4 in working order
12	Wall lights	2 Brushed brass reading lights above the bedside tables	Good condition, no marks or defects noted. Tested, in working order
13	Heating	Underfloor heating beneath the carpet, controlled by a wall thermostat	Good condition, no marks or defects noted. Not tested
14	Air conditioning	1 Ceiling recessed white linear air conditioning grille with a wall controller	Good condition, no marks or defects noted. Not tested

BEDROOM ONE

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS				
15	Switches	3	Brushed brass screwless light switch units, including two beside the bed	Working condition. Visually safe
16	Sockets	4	Brushed brass screwless double plug socket units, two with USB outlets beside the bed	Working condition. Visually safe
17	Fitted wardrobes	1	Full-height fitted wardrobes, four warm white matt lacquer doors with push-to-open catches Interior: brushed brass hanging rails, six oak shelves and integrated LED lighting	Clean and good condition. Interior lighting tested, in working order
DÉCOR AND FURNITURE				
18	Bed	1	King size bed with an upholstered oatmeal linen headboard and base Pocket sprung mattress with a white mattress protector	Clean and good condition, no marks or defects noted. FFR label present.
19	Bed linen		White cotton duvet cover, fitted sheet and four pillowcases, one duvet and four pillows	Clean and freshly laundered

BEDROOM ONE

FINDINGS


ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DÉCOR AND FURNITURE				
20	Bedside tables	2	Oak bedside tables with one drawer each	Good condition, no marks or defects noted
21	Table lamps	2	Ceramic table lamps with linen shades, on the bedside tables	Good condition, no marks or defects noted. Tested, in working order
22	Bench	1	Upholstered oatmeal boucle bench at the foot of the bed	Clean and good condition, no marks or defects noted. FFR label present.
23	Artwork	1	Framed landscape print in a light oak frame, above the bed	Good condition, no marks or defects noted

Bedroom One

PHOTOS



02/02/2026



Item 7 · Flooring

02/02/2026

Bedroom One

PHOTOS



**Window reveal, lower
corner**

Sample photograph placeholder

Item 5 · Window reveal

02/02/2026



**Fitted wardrobes, doors
open**

Sample photograph placeholder

Item 17 · Fitted wardrobes

02/02/2026



Headboard and FFR label

Sample photograph placeholder

Item 18 · Bed

02/02/2026

Bedroom One

PHOTOS



Bedside table and lamp

Sample photograph placeholder

Item 20 · Bedside tables

02/02/2026



Curtains and window

Sample photograph placeholder

Item 6 · Curtains

02/02/2026



Wall lights

Sample photograph placeholder

Item 12 · Wall lights

02/02/2026

BEDROOM TWO



Doors x1



Windows x1



Wardrobes x1

Bedroom Two

NOTE ANY RECENT WORKS

None advised at the time of inspection.

KEY

- Doors
- Windows
- Wardrobes

BEDROOM TWO

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DOORS AND WINDOWS				
1	Door and features	1	Warm white painted solid timber door to both faces, flush finish, concealed hinges Brushed brass lever handles to both faces	Good condition, no marks or defects noted
2	Door frame	1	Warm white painted timber, exposed to both faces	Good condition, no marks or defects noted
3	Threshold	1	Solid oak threshold beneath the door	Good condition, no marks or defects noted
4	Window and features	1	Floor-to-ceiling aluminium framed double glazed window, one tilt and turn opening section Brushed brass handle and lock	Good condition, no marks or defects noted. Not tested
5	Blinds	1	Oatmeal fabric blackout roller blind in a recessed pocket, chain operated	Good condition. Tested, in working order
FLOORING, WALLS AND CEILING				
6	Flooring		Oatmeal wool carpet, fitted wall to wall	Clean and good condition, no marks or defects noted
7	Skirting		Warm white painted timber with a recessed shadow gap	Good condition, no marks or defects noted

BEDROOM TWO

FINDINGS

ITEM	QTY	DESCRIPTION	CONDITION COMMENTS
FLOORING, WALLS AND CEILING			
8	Walls	Warm white painted	Recently filled and painted. Good condition, no marks or defects noted
9	Ceiling	Warm white painted	Good condition, no marks or defects noted
FIXTURES AND FITTINGS			
10	Lighting	3 Recessed ceiling downlights with brushed brass trims, dimmable	Tested, in working order. All 3 in working order
11	Heating	Underfloor heating beneath the carpet, controlled by a wall thermostat	Good condition, no marks or defects noted. Not tested
12	Switches	1 Brushed brass screwless light switch unit, one function	Working condition. Visually safe
13	Sockets	3 Brushed brass screwless double plug socket units, one with USB outlets at desk height	Working condition. Visually safe

BEDROOM TWO

FINDINGS

ITEM	QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS			
14	Fitted wardrobe	1	Full-height fitted wardrobe, two warm white matt lacquer doors with push-to-open catches
			Clean and good condition, no marks or defects noted
		Interior: brushed brass hanging rail and three oak shelves	
DÉCOR AND FURNITURE			
15	Bed	1	Double bed with an upholstered oatmeal linen headboard and base
			Clean and good condition, no marks or defects noted. FFR label present.
		Pocket sprung mattress with a white mattress protector	
16	Bed linen		White cotton duvet cover, fitted sheet and two pillowcases, one duvet and two pillows
			Clean and freshly laundered
17	Bedside table	1	Oak bedside table with one drawer
			Good condition, no marks or defects noted
18	Desk	1	Oak desk with one drawer and brushed brass legs
			Good condition, no marks or defects noted

BEDROOM TWO

FINDINGS


ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DÉCOR AND FURNITURE				
19	Desk chair	1	Upholstered oatmeal desk chair on an oak swivel base	Clean and good condition, no marks or defects noted. FFR label present.
20	Desk lamp	1	Brushed brass adjustable desk lamp	Good condition, no marks or defects noted. Tested, in working order

Bedroom Two

PHOTOS



02/02/2026



Item 8 · Walls

02/02/2026

Bedroom Two

PHOTOS



Bed and headboard

Sample photograph placeholder

Item 15 · Bed

02/02/2026



Fitted wardrobe, doors open

Sample photograph placeholder

Item 14 · Fitted wardrobe

02/02/2026



Carpet and skirting

Sample photograph placeholder

Item 6 · Flooring

02/02/2026

Bedroom Two

PHOTOS



Desk, chair and lamp

Sample photograph placeholder

Item 18 · Desk

02/02/2026



Window and blind

Sample photograph placeholder

Item 5 · Blinds

02/02/2026



Bedside table

Sample photograph placeholder

Item 17 · Bedside table

02/02/2026

BATHROOM



Extractor x1



Windows x0



Toilets in area x1

Bathroom

NOTE ANY RECENT WORKS

None advised at the time of inspection.

KEY

- Extractor
- Windows
- Toilets in area

BATHROOM

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DOORS AND WINDOWS				
1	Door and features	1	Warm white painted solid timber door to both faces, flush finish, concealed hinges Brushed brass lever handles to both faces Interior: brushed brass thumb turn privacy lock	Good condition, no marks or defects noted
2	Door frame	1	Warm white painted timber, exposed to both faces	Good condition, no marks or defects noted
3	Threshold	1	Marble-effect porcelain threshold beneath the door	Good condition, no marks or defects noted
4	Windows		Nil recorded	Nil recorded
FLOORING, WALLS AND CEILING				
5	Flooring		Large-format white marble-effect porcelain tiles with pale grey grouting	Clean and good condition, no marks or defects noted
6	Walls		Large-format white marble-effect porcelain tiles floor to ceiling with pale grey grouting	Clean and good condition, no marks or defects noted
7	Ceiling		Warm white painted, moisture resistant	Good condition, no marks or defects noted

BATHROOM

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS				
8	Lighting	4	Recessed ceiling downlights with brushed brass trims, dimmable	Tested, in working order. All 4 in working order
9	Extractor fan	1	Ceiling recessed white extractor, runs with the lighting	Tested, in working order
10	Heating		Underfloor heating beneath the porcelain floor	Good condition, no marks or defects noted. Not tested
11	Towel rail	1	Wall mounted brushed brass heated towel rail	Good condition, no marks or defects noted. Not tested
12	Switches	1	Brushed brass screwless light switch unit outside the door, one function	Working condition. Visually safe
13	Sockets	1	Brushed brass shaver socket unit beside the mirror	Working condition. Visually safe
14	Bath	1	Freestanding white acrylic double ended bath	Clean and good condition. Filler tested, in working order
			Floor standing brushed brass bath filler with hand shower	

BATHROOM

FINDINGS

ITEM	QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS			
15	Shower	1	Walk-in shower with a frameless clear glass screen and brushed brass wall bracket
			Brushed brass thermostatic mixer, ceiling mounted rain shower head and hand shower on a rail
			Low profile white stone resin shower tray with a brushed brass linear drain
16	Sealant	1	White silicone sealant to the shower tray and wall joint, the bath surround and the vanity top
17	Vanity unit	1	Wall hung oak vanity unit with two soft close drawers
			White ceramic countertop basin with a wall mounted brushed brass mixer tap
18	Toilet	1	Wall hung white ceramic toilet with a soft close seat and lid, brushed brass flush plate
19	Mirror	1	Wall mounted backlit mirror with demister, touch switch

BATHROOM

FINDINGS


ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS				
20	Accessories	3	Brushed brass toilet roll holder, robe hook and towel ring	Good condition, no marks or defects noted
DÉCOR AND FURNITURE				
21	Stool	1	Round oak stool beside the bath	Good condition, no marks or defects noted
22	Bath mat	1	White cotton bath mat	Clean and freshly laundered

Bathroom

PHOTOS



02/02/2026



Item 16 · Sealant

02/02/2026

Bathroom

PHOTOS



**Shower glass and brushed
brass mixer**

Sample photograph placeholder

Item 15 · Shower

02/02/2026



**Vanity unit and
countertop basin**

Sample photograph placeholder

Item 17 · Vanity unit

02/02/2026



**Wall hung toilet and
flush plate**

Sample photograph placeholder

Item 18 · Toilet

02/02/2026

Bathroom

PHOTOS



Freestanding bath and mixer

Sample photograph placeholder

Item 14 · Bath

02/02/2026



Heated towel rail

Sample photograph placeholder

Item 11 · Towel rail

02/02/2026



Mirror and accessories

Sample photograph placeholder

Item 19 · Mirror

02/02/2026

HALLWAY STORAGE CUPBOARD



NOTE ANY RECENT WORKS

None advised at the time of inspection.

KEY


- Doors
- Storage cupboard
- Alarms



Doors N/A



Storage cupboard N/A



Alarms N/A

Hallway Storage Cupboard

HALLWAY STORAGE CUPBOARD

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DOORS AND WINDOWS				
1	Door and features	1	Warm white painted flush timber door with push-to-open catch, concealed hinges	Good condition, no marks or defects noted
2	Door frame	1	Warm white painted timber, exposed to both faces	Good condition, no marks or defects noted
3	Threshold		No threshold fitted beneath the door	Not present
4	Windows		Nil recorded	Nil recorded
FLOORING, WALLS AND CEILING				
5	Flooring		Wide-plank oak herringbone floor, continued from the hallway	Clean and good condition, no marks or defects noted
6	Walls		Warm white painted	Good condition, no marks or defects noted
7	Ceiling		Warm white painted	Good condition, no marks or defects noted
FIXTURES AND FITTINGS				
8	Lighting	1	Ceiling recessed downlight with a door operated switch	Tested, in working order

HALLWAY STORAGE CUPBOARD

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS				
9	Sockets	2	White plastic double plug socket units at worktop height	Working condition. Visually safe
10	Washer dryer	1	White freestanding washer dryer beneath an oak worktop	Clean and good condition. Tested, in working order
11	Boiler	1	Wall mounted white gas combination boiler, high level	Good condition, no marks or defects noted. Not tested
12	Stopcock	1	Brass stopcock valve at low level, labelled	Good condition, no marks or defects noted. Not tested
13	Fuse box	1	Wall mounted white metal consumer unit with hinged cover, circuits labelled	Good condition, no marks or defects noted. Visually safe
14	Shelving		Fitted oak shelves above the washer dryer, three tiers	Clean and good condition, no marks or defects noted
DÉCOR AND FURNITURE				
15	Vacuum cleaner	1	Cordless stick vacuum cleaner on a wall charging bracket	Good condition, no marks or defects noted. Tested, in working order

HALLWAY STORAGE CUPBOARD

FINDINGS


ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DÉCOR AND FURNITURE				
16	Ironing board and iron	1	Folding ironing board with a grey cover, steam iron	Good condition, no marks or defects noted. Iron tested, in working order
17	Laundry basket	1	Woven laundry basket with a lid	Clean and good condition, no marks or defects noted

Hallway Storage Cupboard

PHOTOS



02/02/2026



Item 10 · Washer dryer

02/02/2026

Hallway Storage Cupboard

PHOTOS



Boiler and pipework

Sample photograph placeholder

Item 11 · Boiler

02/02/2026



Consumer unit, cover open

Sample photograph placeholder

Item 13 · Fuse box

02/02/2026



Stopcock and label

Sample photograph placeholder

Item 12 · Stopcock

02/02/2026

Hallway Storage Cupboard

PHOTOS



**Shelving and vacuum
cleaner**

Sample photograph placeholder

Item 14 · Shelving

02/02/2026



Ironing board and iron

Sample photograph placeholder

Item 16 · Ironing board and iron

02/02/2026



Ceiling light and walls

Sample photograph placeholder

Item 8 · Lighting

02/02/2026

BALCONY



Balcony

NOTE ANY RECENT WORKS

None advised at the time of inspection.

BALCONY

FINDINGS

ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
DOORS AND WINDOWS				
1	Door and features	1	Aluminium framed double glazed sliding door from the reception, bronze finish to the exterior	Good condition, no marks or defects noted. Not tested
2	Threshold	1	Flush aluminium threshold track	Clean and good condition, no marks or defects noted
3	Windows		Nil recorded	Nil recorded
FLOORING, WALLS AND CEILING				
4	Flooring		Grey porcelain paving on pedestals	Clean and good condition, no marks or defects noted
5	Balustrade		Frameless clear glass balustrade with a bronze aluminium top rail	Clean and good condition, no marks or defects noted
6	Walls		Pale stone cladding to the building face	Good condition, no marks or defects noted
7	Soffit		Bronze aluminium soffit panels to the balcony above	Good condition, no marks or defects noted
FIXTURES AND FITTINGS				
8	Lighting	2	Wall mounted bronze outdoor lights	Good condition, no marks or defects noted. Tested, in working order

BALCONY

FINDINGS


ITEM		QTY	DESCRIPTION	CONDITION COMMENTS
FIXTURES AND FITTINGS				
9	Sockets	1	Weatherproof grey outdoor double socket unit with a hinged cover	Working condition. Visually safe
10	Drainage		Linear drainage channel beneath the paving at the building edge	Clear of debris
DÉCOR AND FURNITURE				
11	Lounge chairs	2	Teak framed outdoor lounge chairs with oatmeal outdoor fabric cushions	Clean and good condition, no marks or defects noted. FFR label present.
12	Table	1	Round teak outdoor coffee table	Good condition, light weathering consistent with outdoor use
13	Planters	2	Large grey fibre clay planters with olive trees	Good condition. Plants in healthy condition

Balcony

PHOTOS



02/02/2026



Item 1 · Door and features

02/02/2026

Balcony

PHOTOS



Glass balustrade and top rail

Sample photograph placeholder

Item 5 · Balustrade

02/02/2026



Porcelain paving and drainage channel

Sample photograph placeholder

Item 4 · Flooring

02/02/2026



Lounge chairs and cushions

Sample photograph placeholder

Item 11 · Lounge chairs

02/02/2026

Balcony

PHOTOS



**Sliding door track and
threshold**

Sample photograph placeholder

Item 2 · Threshold

02/02/2026



**Outdoor table and
planters**

Sample photograph placeholder

Item 12 · Table

02/02/2026



**Outdoor lighting and
socket**

Sample photograph placeholder

Item 8 · Lighting

02/02/2026

SIGNATURES

The signatures below state that both parties are happy with the inventory report and its content, 14 working days following receipt of this document. If the property is rented to multiple tenants, one tenant signature denotes the approval of all tenants.

TENANT

NAME

DATE

SIGNATURE

LANDLORD / VERIFIER

NAME

DATE

SIGNATURE

Amendments must be advised in writing by **23/02/2026**. If no amendments are advised within this time, the report will be deemed accepted in full and final by both landlord / managing agent and tenant.